

PLICSRADIO software revision



PLICSRADIO D61

Revision	Description	Available since
1.10	First sales version	03/2007
1.11	-Error correction: temporary deactivation of the PIN caused permanent deactivation up to the next restart -HART-Generic instrument: Sensorvalue (PV) available	05/2008
1.12	-Error correction: Trigger of watchdog during device boot.	05/2008
1.20	- Support for plics@plus sensors	02/2010

PLICSRADIO software revision



PLICSRADIO R6x

Revision	Description	Available since
1.10	First sales version	03/2007
1.11	-Error correction: temporary deactivation of the PIN caused permanent deactivation up to the next restart -HART-Generic instrument: Sensorvalue (PV) available	05/2008
1.12	-Error correction: Trigger of watchdog during device boot.	05/2008
1.20	- Support for plics@plus sensors	02/2010

PLICSRADIO software revision



PLICSRADIO T6x

Revision	Description	Available since
1.10	First sales version	03/2007
1.11	-Error correction: temporary deactivation of the PIN caused permanent deactivation up to the next restart -HART-Generic instrument: Sensorvalue (PV) available	05/2008
1.12	-Error correction: Trigger of watchdog during device boot.	05/2008
1.20	- Support for plics@plus sensors - T61 supports now also sensors in Multidrop mode (address 1)	02/2010